ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M 05485

Date Received: 04/14/10

Date Extracted: 04/16/10

Date Analyzed: 04/16/10

Matrix: Water

Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: Metro Self Monitor, F&BI 004139
Lab ID: 004139-01 x10

Data File: 004139-01 x10.061 Instrument: ICPMS1

Operator: AP

		Lower	Upper
Internal Standard:	% Recovery:	Limit:	Limit:
Germanium	96	60	125

Analyte:	Concentration ug/L (ppb)
Chromium	499
Nickel Copper Zinc	407 351 24.0

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Date Received: Not Applicable Date Extracted: 04/16/10

Date Analyzed: Matrix: Water Units:

Internal Standard:

Germanium

04/16/10 ug/L (ppb)

Client: Project: Alaskan Copper Works

Metro Self Monitor, F&BI 004139

Lab ID: I0-194 mb Data File: I0-194 mb.045 Instrument: ICPMS1 Operator: AP

% Recovery:

101

Lower Limit: 60

Upper Limit: 125

Concentration Analyte: ug/L (ppb) Chromium <1 Nickel <1 <1 Copper Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 04/21/10 Date Received: 04/14/10

Project: Metro Self Monitor, PO M 05485, F&BI 004139

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 004157-01 (Matrix Spike)

				Percent	Percent		
Analyte	Reporting Units	Spike Level	Sample Result	Recovery MS	Recovery MSD	Acceptance Criteria	RPD (Limit 20)
Chromium	ug/L (ppb)	20	1.83	105	113	67-132	7. 7.
Nickel	ug/L (ppb)	20	6.29	92 b	99 b	73-119	7
Copper	ug/L (ppb)	20	1.40	89	94	50-144	5
Zinc	ug/L (ppb)	50	2.87	96	101	46-148	5

Laboratory Code: Laboratory Control Sample

		Percent							
Nickel Copper	Reporting Units	Spike Level	Recovery LCS	Acceptance Criteria					
Chromium	ug/L (ppb)	20	98	66-135					
Nickel	ug/L (ppb)	20	103	67-134					
Copper	ug/L (ppb)	20	102	66-134					
Zinc	ug/L (ppb)	50	103	57-135					

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 21, 2010



Accounts Payable Alaskan Copper Works 628 South Hanford Seattle, WA 98134

RE: Project Metro Self Monitor, PO M 05485, F&BI 004139- Results of testing requested by Gerry Thompson for material submitted on April 14, 2010.

FEDERAL TAX ID #(b) (6)

004139	e e		s SA	MPL	Е СНА	in of c	US7	OP	Y		M	Ð	1	<<)	04-	14	-10		ATY
Send Report To SENGO	دسطار	- · ·		SAM	PLER	si <u>an</u> ature)		_			a		_			Pa	age#		of_	T
			PROJECT NAME/NO. METRO Self Monitor						-8:-	PC) #		TURNAROUND TIME ☐ Standard (2 Weeks)							
Company ALASKAN COFFER Works Address 628 S. Handad St		n							m65485				Rush charges authorized by:							
				REMARKS											SAMPLE DISPOSAL					
City, State, ZIP_SAG	Re W	5. 581	34_	REM	ARKS			9								Disp	ose a	after 30) days	L
Phone #206-571-60	33 Fax # 60	6-382-0	1309	-								34						amples with in	structio	ons
											ANA	LYS	ES R	EQU	EST	ED				
Sample ID	Lab ID	Date	Time	Sam	ple Type	# of containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	HFS	acures						Notes	
mo5485	01	4/14	12:30	14	CO	1				1.00			X							
8																				
											٦								Ø	16
					***************************************				\dashv		7	7							-20.94777	
	597									-				+						
					-	1					1	T								
											1									
							_	7	_							-	-	<u> </u>		
							_		-	+	+	\dashv				-	-		2-5.m2 R	
				-			-	-	-	+	\dashv	\dashv	-							-
Friedman & Bruya, Inc.		SIGNATUE	RE	L		PRINT	NAN	/E	_		L		CO	MPA	NY	L	L_{L}	DATE	т	'IME
3012 16th Avenue West				_ Gerea Thompso					COMPANY				,	13	1/1//	-	BPM			
Seattle, WA 98119- Ph. (206) 285-8282	Received by. Relinquished by:				Than Phan					F-eBI 4/14/10					-	28				
Fax (206) 283-5044	Received by:	-									+	F	21.70	3		_	+		12 g	-
FORMS\COC\COC.DOC		2					N	-												r _a re-

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 21, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on April 14, 2010 from the Metro Self Monitor, PO M 05485, F&BI 004139 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Kortland Orr Project Manager

Enclosures ACU0421R.DOC